

TECHNICAL Data

CT-620 CLEANING TREATMENT

DESCRIPTION: An inhibited, highly concentrated acid used to remove rust, hardwater scale and other accumulations from water cooled equipment, water jackets, heat exchangers and heating coils.

DIRECTIONS: Flush with water. Add 1 part of product to 2 parts warm water. Allow this solution to circulate until scale is removed, usually 30 minutes to 2 hours, depending upon type and amount of scale. In extreme cases it may be necessary to change solution and recirculate. Flush with water for 5 minutes.

CAUTION: DANGER-EXTREMELY CORROSIVE

Contains hydrochloric acid. Avoid breathing vapours. Harmful or fatal if swallowed. Avoid contact with skin and eyes.

FOR COMMERCIAL USE

